

History Snippet of Toyota Tundra that will work with our Toyota Truck Rack

First Generation (2000-2006) continued

As of January 2012, Toyota Motor Co. is recalling 533,000 trucks and SUVs because of possible steering and suspension problems caused by faulty ball joints. The recall marks a sudden shift in policy for the Japanese automaker after repeatedly denying consumer complaints about ball joint problems and failures in the Tundra and Sequoia. The Toyota recall includes 2004 to 2007 model year Sequoia full-size sport utility vehicles and 2004 to 2006 Tundra pickups sold in the U.S. A ball joint in the front suspension may wear out causing the vehicles to be difficult or sometimes impossible to steer. Toyota reports that the defect may be the cause of 11 accidents resulting in six injuries. This can cause the wheel to fall off the truck without any notice. [\[citation needed\]](#)

This Historical info drawn attributed to Wikipedia at https://en.wikipedia.org/wiki/Toyota_Tundra